

COOLWORKS[®]

WORKWEAR

BE SEEN

BE SAFE

BE COMFORTABLE

COOLWORKS GARMENTS WASH AND CARE INSTRUCTIONS

| SKU | Fabric weight: g/m ² or oz./yd ² | Washing instructions: |
|--|---|--|
| CW1* | 220 g/m ² = 6.49 oz./yd ² 100% polyester | Machine wash cold. Do not bleach. Tumble dry, LOW HEAT. Iron, steam or dry with LOW HEAT. Do not dry clean. |
| CW2* | 220 g/m ² = 6.49 oz./yd ² 65%/35% poly/cotton ripstop | Wash with like colours. Machine wash cold on permanent press. Do not bleach. Tumble dry, LOW HEAT. Iron, steam or dry with LOW HEAT. Do not dry clean. |
| TS1000* | 125 g/m ² = 4.41 oz./yd ² 100% polyester | Machine wash warm. Do not bleach. Tumble dry on permanent press, LOW HEAT. Iron, steam, or dry with MEDIUM HEAT. |
| TS1103* TS1104* TS1203* TS1204* | 180 g/m ² = 5.64 oz./yd ² 100% polyester | Machine wash warm. Do not bleach. Tumble dry on permanent press, LOW HEAT. Iron, steam, or dry with MEDIUM HEAT. |

*** Improper laundering voids warranty**

Coolworks Workwear Inc.

Mailing Address - 701 Trinity Rd. : Units 4 & 5, Jerseyville , ON, L0R 1R0

Shipping Address - 701 Trinity Rd. : Units 4 & 5, Ancaster , ON, L9G 3L1

Phone (905) 648-9994 Toll Free 1- 888-689-9548 Fax (905) 648-2660

www.coolworksworkwear.com

info@coolworksworkwear.com